

Oil Field Environmental Incident Summary

Incident: 20160825103928 **Date/Time of Notice:** 08/25/2016 10:39
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: SCOTT 31-36H
Field Name: MURPHY CREEK **Well File #:** 17989
Date Incident: 8/24/2016 **Time Incident:** 14:00 **Facility ID Number:**
County: DUNN **Twp:** 144 **Rng:** 96 **Sec:** 36 **Qtr:** NE NW
Location Description: Single Well pad. Landowner has a fence adjacent field next to location

Submitted By: Josey Adams **Received By:**

Contact Person: Josey Adams
600 N. DAIRY ASHFORD
HOUSTON, TX 77079

General Land Use: Well/Facility Site **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 4000 Feet

Distance Nearest Water Well: 4000 Feet

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 12/22/2016 **Clean Up Concluded:** 11/18/2016

Risk Evaluation:

None

Areal Extent:

Area was 25 feet by 25 feet

Potential Environmental Impacts:

Damage to grass. Area will be remediated.

Action Taken or Planned:

Work order was put in to clean-up spill and remediate area.

Wastes Disposal Location: Contaminated soil will be disposed of at Tervita disposal

Agencies Involved:

Updates

Date: 8/25/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 1 barrel of treater oil went into a nearby field. More follow-up is needed.

Date: 9/1/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 9/1/2016, at 12:31 p.m. Release impacted area to the north off location. Area has been mowed (approximately 80 X 60 ft). There are still some noticeable impacts and stains on the soils. A sample was collected at the site. Will speak to contact to discuss further remediation plans. Soil and garbage bags are stockpiled on location awaiting disposal. More follow-up required.